

ಕರ್ನಾಟಕ ಸರ್ಕಾರ
(ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ)

ಕ್ರ.ಸಂ.ಲೋ.ಇ./ಉ.ವಿ.ಬಿ./ಸ.ಇಂ/ಕ.ಸ.ಪ್ರಪ/2021-22/

957

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ಉಪ ವಿಭಾಗ, ಬೆಳಗಾವಿ ಇವರ ಕಚೇರಿ.

7/9/2021

ಇವರಿಗೆ,

ಅಧ್ಯಕ್ಷರು,
ಮಹೇಶ ಪೌಂಡೇಶನ್
ಸಿದ್ಧೇಶ್ವರ ನಗರ, ಕಣಬರ್ಗಿ,
ಬೆಳಗಾವಿ

ಮಾನ್ಯರೇ,

ವಿಷಯ: ಮಕ್ಕಳ ಪಾಲನಾ ಸಂಸ್ಥೆಗೆ ಕಟ್ಟಡದ ಫಿಟ್ಟೆಸ್ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡುವ ಕುರಿತು.

ಉಲ್ಲೇಖ: ತಮ್ಮ ಅರ್ಜಿ ದಿನಾಂಕ: 02-09-2021.

ಮೇಲ್ಕಾಣಿಸಿದ ವಿಷಯ ಹಾಗೂ ಉಲ್ಲೇಖಿತ ಪತ್ರದನ್ವಯ, ಮಹೇಶ ಪೌಂಡೇಶನ್ ಸಂಸ್ಥೆಯ (ಎಚ್.ಐ.ಐ. ಮಕ್ಕಳಿಗೋಸ್ಕರ ಸುಸಜ್ಜಿತ ಕಟ್ಟಡ) ಕಟ್ಟಡವು ಸುರಕ್ಷಿತವಾಗಿರುವ ಬಗ್ಗೆ ದೃಢೀಕರಣ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಕೋರಿರುತ್ತೀರಿ.


ಸದರಿ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ: 06-09-2021 ರಂದು ಪರಿವೀಕ್ಷಿಸಲಾಗಿ ಹಾಗೂ GOGTE INSTITUTE OF TECHNOLOGY Udyambag Belagavi. ಇವರಿಂದ ಪಡೆದಿರುವ Fitness Certificate ಅನ್ನು ಆಧರಿಸಿ, ಸದರಿ ಕಟ್ಟಡವು ಸುಸ್ಥಿತಿಯಲ್ಲಿದ್ದು, ಈ ಕೆಳಕಂಡ ಷರತ್ತುಗಳನ್ನು ಅಳವಡಿಸಿ ಕಟ್ಟಡವು ತರಗತಿಗಳನ್ನು ನಡೆಸಲು ಯೋಗ್ಯವಾಗಿದೆ ಎಂದು ಪ್ರಮಾಣೀಕರಿಸಲಾಗಿದೆ.

ಷರತ್ತುಗಳು :

1. ಮುಂದಿನ ದಿನಗಳಲ್ಲಿ ಕಟ್ಟಡದ ಯಾವುದೇ ಭಾಗದಲ್ಲಿ ಕುಸಿತ/ಬಿರುಕು/ನೀರು ಸೋರುವಿಕೆ ಇತ್ಯಾದಿ ತೊಂದರೆಗಳು ಕಂಡು ಬಂದಲ್ಲಿ ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರಕ್ಕೆ ಕೂಡಲೇ ವರದಿ ನೀಡುವುದು.
2. ಕಟ್ಟಡದ ಮೂಲ ದಾಖಲೆಗಳನ್ನು ಸರಿಯಾಗಿ ನಿರ್ವಹಿಸುವುದು.

ಸದರಿ ಪ್ರಮಾಣ ಪತ್ರವು ಸನ್ 2021-22 ನೇ ಸಾಲಿಗೆ ಮಾತ್ರ ಅನ್ವಯಿಸುತ್ತದೆ, ಸದರಿ ಸಂಸ್ಥೆಯ ಕಟ್ಟಡವು ತರಗತಿಗಳನ್ನು ನಡೆಸಲು ಯೋಗ್ಯವಾಗಿದೆ ಎಂದು ಈ ಮೂಲಕ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,


ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು,
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ,
ಉಪ ವಿಭಾಗ ನಂ.1, ಬೆಳಗಾವಿ



KARNATAK LAW SOCIETY'S
GOGTE INSTITUTE OF TECHNOLOGY
"JNANA GANGA" UDYAMBAG, BELAGAVI-590 008, KARNATAKA, INDIA.



Approved by All India Council for Technical Education (AICTE), New Delhi and UGC section 2(f) & 12(B). Permanently Affiliated and Autonomous Institution under Visvesvaraya Technological University, Belagavi. *Accredited by National Board of Accreditation (NBA), New Delhi. Accredited by National Assessment and Accreditation Council (NAAC) with **A+ Grade**
Tel:(Off):+91-831- 2498500, 2405506 • Fax:+91-831- 2441909 • e-mail:principal@git.edu • Visit us @ www.git.edu

CERTIFICATE

It is certified that the Building of Mahesh Foundation at 792/1, Opposite Government Kannada School, Siddeshwar Nagar, Kanabargi, Belagavi belonging to Mahesh Foundation Belagavi was inspected on 31-08-2021 and found to be fit for its intended use with reference to the inspection report enclosed.

Place: Belagavi

Date: 01-09-2021

Building Inspected by

Prof. Rajendra J. Thakai





HOD
PROFESSOR & HEAD
Civil Engineering Department
Gogte Institute of Technology,
Udyambag, Belagavi - 590 008

REPORT OF BUILDING FITNESS

- | | |
|--|---|
| 1. Building Belonging to | : Mahesh Foundation Belagavi |
| 2. Building Address | : 792/1, Opposite Government Kannada School, Siddeshwar Nagar, Kanabargi, Belagavi. |
| 3. Description / Classification of Building | : R.C.C framed structure Ground + 04 floor building. |
| 4. Test conducted | : NDT (Rebound Hammer Test) has been conducted on columns, beams and slab at random locations and strength of concrete was obtained in the range of 30 N/mm^2 to 35 N/mm^2 which is found to be satisfactory. |
| 5. Nature of Defects observed, if any | |
| a. Foundations & Basement | : Nil |
| b. Superstructure | : Nil |
| c. Doors & Windows | : Nil |
| d. Wood work | : Nil |
| e. Roof | : Nil |
| f. Flooring | : Nil |
| g. Miscellaneous (Crack, etc) | : Nil |
| 6. Any Major Defects noticed which will render the building unsafe in any manner | : Nil |
| 7. Whether maintenance works have been done properly | : Yes |
| 8. Whether the structure is sound or not for Occupancy | : Yes, structure is sound |



**Building Inspection of Mahesh Foundation Siddeshwar Nagar, Kanabargi,
Belagavi.**



**Building Inspection of Mahesh Foundation Siddeshwar Nagar, Kanabargi,
Belagavi,**

